

**MATERIAL
SAFETY DATA
SHEET**

Bocchi Laboratories

26421 Ruether Avenue, Santa Clarita, CA 91350

FOR ALL EMERGENCIES, CALL CHEM TEL (24 Hours/7 Days):	1-813-979-0626
UNITED STATES & CANADA ONLY:	1-800-255-3924
INTERNATIONAL:	00-1-813979-0626
FOR ALL MSDS QUESTIONS OR REQUESTS, CALL:	1-661-252-3807

1. PRODUCT IDENTIFICATION

PRODUCT CLASS: HAIR STYLER
PRODUCT NAMES: DAVEXLABS HEALING SMOOTH THERMAL DEFENSE
MANUFACTURER: BOCCHI LABORATORIES, INC.
26421 RUEETHER AVENUE, SANTA CLARITA, CA-91350

REVISION DATE:	ORIGINAL (10/09)
SUPERCEDES:	N/A
MSDS NO:	DAV-079

2. COMPOSITION/INFORMATION ON INGREDIENTS

Chemical characterization

Description:

Formulations designed to provide texture, definition and conditioning to the hair.

Hazardous Components:

Ingredient	CAS No.	EINECS No.	Percent	Hazardous
Ethyl Alcohol	64-17-5	200-578-6	55%	Yes

3. HAZARDS IDENTIFICATION

POTENTIAL HEALTH EFFECTS

EYE CONTACT: Direct contact of product with eyes may cause irritation, and may result in irreversible damage.

SKIN CONTACT: Not Known

INHALATION: Not Known

INGESTION: If ingested, may cause nausea and vomiting. If in aerosol form, ingestion is not likely.

4. FIRST AID MEASURES

EYE CONTACT: If irritation or redness due to vapors develops, move victim away from exposure and into fresh air. If material gets into the eyes, flush eyes immediately with clean water for at least 15 minutes. If available, use eye-cups or eye wash fountain. If symptoms persist, get medical attention.

SKIN CONTACT: Clean affected areas with mild soap and water. Remove contaminated clothing, including shoes, and launder before reuse or discard. Call a physician if irritation develops.

INHALATION: If respiratory symptoms develop, move victim away from source of exposure and into fresh air. If symptoms persist, get medical attention. If victim is not breathing immediately begin artificial respiration. Get medical attention.

INGESTION: Product is not likely to be ingested. If this occurs, treat systematically. Never give fluids or induce vomiting if the victim is unconscious or having convulsions

5. FIRE FIGHTING MEASURES

Flammability Summary (OSHA): Product is flammable.

Flammable Properties

Flash Point: <65° Fahrenheit

Fire/Explosion Hazards: Material may be ignited, for example in a fire. Relative hazard is anticipated to be the same as typical combustible materials.

Extinguishing Media: Use foam, carbon dioxide, and dry chemical or water spray when fighting fires.

Fire Fighting Instructions: In case of fire, use normal fire fighting equipment including a NIOSH approved self-contained breathing apparatus (SCBA). Use water to cool containers.

Hazardous Combustion Products: Carbon Dioxide, Carbon Monoxide

6. ACCIDENTAL RELEASE MEASURES

SPILL ON LAND (LARGE SPILL): Eliminate sources of ignition. Prevent additional discharge of material, if possible to do so without risk. Minimize breathing of vapors. Minimize skin contact. Ventilate confined spaces. For small spills implement the following cleanup procedures: Prevent material from entering sewers, watercourses, or low areas. Contain spilled material with sand or earth. Do not use combustible materials such as sawdust. Observe precautions for volatile, combustible vapors from absorbed material. For large spills implement the preceding cleanup procedures and, if in public area, keep public away and advise authorities. Consult an expert on disposal of recovered material and ensure conformity to local disposal regulations.

SPILL ON WATER (LARGE SPILL): Eliminate sources of ignition. Warn occupants and shipping in surrounding and downwind areas of fire and explosion hazard and request all to stay clear. Remove from surface by skimming or scooping up floating material. Consult an expert on disposal of recovered material and ensure conformity to local disposal regulations.

SMALL SPILLS: Leaking containers should be placed in open containers, outdoors, away from any source of ignition, until all pressure has been released.

7. HANDLING AND STORAGE

STORAGE TEMPERATURE: Ambient

LOADING/UNLOADING TEMPERATURE: Ambient

STORAGE AND HANDLING: Keep container closed. Handle and open containers with care. Store in a cool, well-ventilated place away from incompatible materials. DO NOT handle or store near an open flame, heat, or other source of ignition. DO NOT pressurize, cut, heat, or weld empty containers. DO NOT reuse containers.